

Letter aircellR



RAJASTHAN RAJYA VIDYUT PRASARAN NIGAM LIMITED  
[Corporate Identity Number (CIN) : U40109RJ2000SGC016485]  
OFFICE OF THE SUPERINTENDING ENGINEER(QC-Inspection & Monitoring)  
Regd. Office: VidyutBhawan, Jyoti Nagar, Jaipur -302005  
(AN ISO 9001: 2015 CERTIFIED COMPANY)  
E-mail: se.qc.insp@rvpn.co.in; Website: www.rvpn.co.in

No. RVPN/SE/QC-Insp. & Montg./ XEn-2/Insp./F./ID 808

Dated 5-3-19


The Superintending Engineer ( T&C)- All Circle  
Rajasthan Rajya Vidyut Prasaran Nigam Ltd.,

**Sub :-** Pending shortcomings related to Air cell inflation, improper yard light & painting of Structure/equipments observed by T&C wing officers (SE & above)during inspection in FY 2018-19.

This has reference to the compliance report sent by various circle officers (T&C wing) of their observations/shortcomings noted during inspection in FY 2018-19 . Based on circle wise compliance of shortcomings/observations of the inspection reports received by this office, it has been observed that in general, most of the observations of the inspection reports are being regularly rectified by the field officers except few in which following are mainly shortcomings which are still pending for rectification.

1. **Air cell inflation in main conservator of transformer:** As intimated by the field officers, the action has been taken in the above matter with the firm or purchase action has been initiated for replacement of aircell. In this matter, recently XEn (220 kV GSS), Nagaur has recently purchased the aircell and attended the aircell related shortcoming. So the concerned field officers may be advise for any assistance, if required from XEN( 220 kV GSS) Nagaur who has recently purchased and replaced the aircell.
2. **Painting of Structure/Equipments:** In cases where GSS in-charge is not able to attend painting of structures/equipment at their own level, the shortcomings may be rectified by providing necessary assistance for initiating tender. Efforts are to be made to expedite the rectification of above shortcoming at the earliest.
3. **Lightning of GSS (yard/road light):**
  - i) **R&M/replacement of yard light:** Sufficient nos. of yard light have been procured by procurement wing and the same are allotted to concerned(T&C) circle as per their requirement (Jaipur/Ajmer/Jodhpur). The yard lights may be allotted/issued to the GSS in-charge so that the above shortcomings are rectified at the earliest.
  - ii) **Yard lights requirement for newly commissioned GSS:** During construction of GSS, concerned SE(T&C) should properly take up the matter of installation of yard light with C&M officers and it should be ensured by SE(T&C) that yard lights are installed before closing of the project.

In view of the above, it is requested to look into the matter personally and expedite the rectification of above mentioned shortcomings at the earliest.

  
5/3/2019  
(R.K Gupta)

Superintending Engineer(QC-inspection & Montg.)