



CIN:U40109RJ2000SGC016486

Jaipur Vidyut Vitran Nigam Limited

Regd. Office: Vidyut Bhawan, Janpath, Jaipur-5

Tel:-0141-2742064 Fax-0141-2743015

Website: www.jaipurdiscom.com

E-mail: md@jvvn.in

No.JPD /MD/TA/F. /D. 432

Jaipur, dt: 9/11/2016

The Superintending Engineer(O&M/JCC/JPDC),
Jaipur Vidyut Vitran Nigam Ltd.,
Jaipur/Alwar/Dausa/Tonk /Bharatpur/Dholpur/Karauli/
Sawaimadhapur/Kota/Bundi/Baran/Jhalawar

Sub:- Block Supply Rotation.

It has been observed that the blocks of agriculture supply are rotated arbitrarily at various 33/11 Sub-stations which is causing a disturbance in flattening the load curve.

It is directed that henceforth, all the blocks must be rotated from commencement of C-Block on each Monday i.e. A-Block which was running in Sunday night will get the supply in C-Block of Monday, similarly the B-Block running in Sunday night will get the supply in the D-Block of Monday. This rotation procedure must be followed religiously in each circle and strict monitoring be ensured by the circle SEs.

sd/-

(Anil Bohra)
Managing Director

Copy to the following for information and necessary action:-

1. Director (Tech.), Jaipur Discom, Jaipur
2. TA to Chairman Discoms, Jaipur
3. TA to Advisor (Energy), GoR Jaipur
4. PS to Secretary, Energy, GoR, Jaipur

Managing Director

Muz top

Cet

Mr. Poojap

San 7 to 10

SEs

10/14