

No. Chairman (Discoms)/F.TA/D: 393 Jaipur, Dated: 28/09/2018.

STANDING ORDER NO. 18/13

It has come to notice that the services of Superintending Engineer(s) are also being utilized for inspection of material procured through MM-wing and/or for Trunkey works by TW-wing.


The Superintending Engineers are quite senior officers and generally head a circle. Absence of Superintending Engineers for routine material inspection work besides adversely affecting their earmarked/ designated functions/ role/work/duties may also hamper the performance of whole circle. It is also felt that material inspection can be more efficiently carried by younger officers of the level of Executive Engineers and Assistant Engineers.


It is therefore enjoined that nominations of Superintending Engineer and above level officers may be avoided for routine inspections of materials procured/arranged through/under MM or TW wing.


(R.G.Gupta) 28/9
Chairman Discoms

Copy to the following for information and necessary action:-

1. CE/ACE () Jaipur/ Ajmer/ Jodhpur Discom _____
2. ZCE () Jaipur/Ajmer/Jodhpur Discom _____
3. SE (O&M/ BT), Jaipur/ Ajmer/ Jodhpur Discom, Jaipur/ Ajmer/Jodhpur/ _____
4. Addl.SP (Vig.), Jaipur/Ajmer/Jodhpur Discom, Jaipur/Ajmer/ Jodhpur
5. CCOA, Jaipur/Ajmer/Jodhpur Discom, Jaipur/Ajmer/Jodhpur
6. CAO (Revenue & Control)/ FM-W&M/ (I/A)/ Consultant (ATR), Jaipur/ Ajmer/ Jodhpur Discom _____
7. Secy. (Admn.), Jaipur/ Ajmer/ Jodhpur Discom, Jaipur/ Ajmer/ Jodhpur.
8. Company Secretary, Jaipur/ Ajmer/ Jodhpur Discom, Jaipur/ Ajmer/ Jodhpur
9. TA to Chairman & Managing Director, Jaipur Discom, Jaipur
10. TA to MD Ajmer/ Jodhpur Discom, Ajmer/ Jodhpur.
11. PA to Dir. (Tech/Fin), Jaipur/ Ajmer/ Jodhpur Discom, Jaipur/ Ajmer/ Jodhpur.


(S.K.Rajput)
TA to Chairman Discoms


Xerox IT-I 2546
Pl. forward to 31/10/18
m/s \$ky209 alho

A-7
AX
4/17