


OFFICE OF THE  
CHAIRMAN DISCOMS,  
JVVNL,AVVNL,JDVVNL,  
Vidhyut Bhawan, Jyoti Nagar, Jaipur 302005  
Phone Office 0141-2747064, Fax- 0141-2747015

---

No.Chairman-Discoms/TA/F. /D. 74 Jaipur, dated 14.2.2014

**ORDER – 14/08**

It has been observed that in all the three Discoms, 33/11KV sub stations are being commissioned without proper and adequate installation of circuit breakers, feeder meters and roster switches. Such technically incomplete commissioning of the sub stations gives rise to the problems such as high interruptions, uncontrolled supply on the 11KV feeders etc. It is, therefore, hereby ordered that in future, no 33KV sub stations shall be energised without adequate and proper installation of circuit breakers, feeder meters and roster switches.

  
(R.G.Gupta)

Chairman Discoms,Rajasthan

Copy to the following for information and necessary action:-

1. The Managing Director, JVVNL, AVVNL, Jd.VVNL, Jaipur/Ajmer/Jodhpur
2. The Director(Tech), JVVNL/AVVNL/Jd.VVNL, Jaipur/Ajmer,Jodhpur
3. The Chief Engineer( ), JVVNL/Jd.VVNL/AVVNL, Jaipur/Ajmer/Jodhpur
4. The Superintending Engineer( ), JVVNL/AVVNL/Jd.VVNL, .....

  
14/02/2014  
TA to Chairman Discoms,Rajasthan