

JAIPUR VIDYUT VITRAN NIGAM LIMITED
(COMMERCIAL WING)

JPR-5-309

NO.JPD/DY.CE(CP&RE)/SE(C)//F.4(24)V/D.2321 Dec15, 2005

ORDER


Sub: Procedure to be followed when LT Trivector meter installed at the premises of MIP consumers cease to display readings.

Detailed procedure to be followed in the eventuality when the HT Trivector meter installed at the premises of a consumer ceases to display readings has been prescribed vide Jaipur Discoms order No.1527 dt. 12.9.03 (JPR5-135). In the said order, various steps required to be taken by the concerned field officers have been indicated in seriatum.

It has been observed that there are cases when the LT Trivector meters installed at the premises of MIP consumers ceases to display the readings. In line with the procedure prescribed for HT Trivector meters, it has been decided to prescribe the same procedure but with the following modifications:-

- I) The joint inspection report after the LT Trivector meter has ceased to display readings is required to be prepared by AEn (O&M)/Meters instead of XEn (O&M)/Meters.
- II) The AEn (Meter) is required to take the permission of SE (Meter) for sending the meter to manufacturer's works for finding out the meter reading as well as the load survey in presence of the representatives of the Meter Wing and consumers at the manufacturers works.
- III) On receipt of approval of SE (meter) the AEn (Meter) is required to obtain the data from the manufacturer for testing of the meter and retrieving of the readings . In the Order JPR5-135 the data was prescribed to be taken by the XEn (Met.).

my
The procedure however, would remain the same as prescribed under the order JPR5-135. Above instructions should be strictly complied with by all field officers.



(B.L.Agrawal)

Dy.Chief Engineer (CP&RE)