

JPR5-394

JAIPUR VIDYUT VITRAN NIGAM LIMITED
OFFICE OF THE CHIEF ENGINEER (COMMERCIAL)
VIDYUT BHAWAN, JYOTI NAGAR, JAIPUR 302 005

No. JPD/CE(C)/SE(C)/C.I/F.4(261)/Pt.VI/D. 648 Dt. 19.04.07

ORDER

Sub: Multiplying factor be also mentioned in words apart from numerical number, in joint inspection report.

It has been observed that while preparing joint inspection report by Meter Wing, the multiplying factor is some times mentioned in numerical numbers only. At times the multiplying factor written in number form is not legible/clear and, therefore, there are chances of issuing wrong bills.

This matter came up for discussion in the Corporate Level Settlement Committee meeting held on 13-3-07 and 24-3-07. It was decided that in future the multiplying factor must be written in the numerical form as well as in so that chances of issuing bills on the basis of wrong multiplying factor are ruled-out. Failing to comply with these instructions, disciplinary action would be initiated against defaulting officers.

hury

By order,


(B.L. Agarwal)

Chief Engineer (Comml.)