

Burnt Transformer Replacement Report - Sep'18

S. No	Lifter Deployed	Circle	Replace within 6 Hrs
1	Malakheda	Alwar	155
2	K.G.Bas	Alwar	
3	Baran	Baran	57
4	Atru	Baran	
5	Bundi	Bundi	52
6	Dausa	Dausa	62
7	Aklera	Jhalawar	60
8	Jhalawar	Jhalawar	69
9	Shahpura	JPDC	50
10	Chomu	JPDC	
11	Mansarover	JPDC	
12	Tonk	Tonk	19
Total Count			524