


H Schedule for Emergent Repair work for 132 KV S/C Tinwari-Chamu Line

S.N.	Particularsof work	unit	Qty	Rate	Amount	Remaks
1	2	3	4	5	6	
1	Repairing of damaged ACSR Panther Conductor & jointing of conductor, Restringing of conductor between Loc. No. 18 & 19. Detensioning, dehoisting of insualtors as required & hoisting of insualtor string, fitting of PA rods, vibration dampers & clamping etc	JOB	1			
	Grand Total					


Assistant Engineer
(T&C) RVPN, DECHU