



प्रभास्मि शशि सूर्ययोः

No.JPD/SE (IT)/F.TN-64/D. 1673

Dated. 9-1-19

ORDER

Pursuant to the inspection of video wall room installed in corporate office, Vidyut Bhawan, Jaipur by the Pr. Secretary (Energy) & Chairman Discoms & and undersigned on 04.01.2019, it was observed that T&D losses on so many 11KV feeders are on the negative side or on much more higher side.

It is therefore enjoined upon all concerned AEN(O&M) to verify and correct each and every figure of T&D loss showing in the www.bijliprabandh.com and complete the task latest by 15.02.2019.

The ZCE (O&M), circle SE (O&M) and XENs (O&V) shall ensure that the above task is completed within time schedule with correct data.

(A. K. Gupta)
Managing Director

Copy to the following for information and necessary action:-

1. The ZCE (JZ/KZ/BZ), JVVNL, Jaipur/Kota/Bharatpur.
2. The ACE (M&P-IT), JVVNL, Jaipur.
3. The SE (JCC/JPDC/O&M), JVVNL,
4. The TA to the MD, JVVNL, Jaipur.
5. The TA to the Director (Tech.), JVVNL, Jaipur.
6. The TA to Chairman Discoms for kind perusal of the Hon'ble Chairman Discoms.
7. The XEN (O&V/), JVVNL,
8. The AEN (), JVVNL,

Superintending Engineer (IT)
Jaipur Discom, Jaipur.